

Inspection Photos

Location Name: Vera L McCannon 1 TANK Battery 5

Location ID: 317643



Photo 1 entrance to site



Photo 2 production equipment and generator

Inspection Photos
Location Name: Vera L McCannon 1 TANK Battery 5
Location ID: 317643



Photo 3 tank battery and berm



Photo 4 tank battery and berm

Inspection Photos
Location Name: Vera L McCannon 1 TANK Battery 5
Location ID: 317643



Photo 5 production equipment



Photo 6 out of service ECD due to fire

Inspection Photos
Location Name: Vera L McCannon 1 TANK Battery 5
Location ID: 317643




Photo 7 stained crude tank




Photo 8 stained soil

Inspection Photos
Location Name: Vera L McCannon 1 TANK Battery 5
Location ID: 317643



Photo 9 stained soiled



Photo 10 stained soil