

Location ID: 427153



Energy and Carbon Management Commission
40.47169, -104.39415, 4760.4ft
01/24/2024 11:58:04

Photo 2 – ECDs

Inspection Photos
Location Name: Wells Ranch AA 24 ECONODE
Location ID: 427153



Photo 3 – Tank Battery



Photo 4 – Water Tanks

Inspection Photos
Location Name: Wells Ranch AA 24 ECONODE
Location ID: 427153



Photo 5 – Water Tanks



Photo 6 – VRTs

Inspection Photos
Location Name: Wells Ranch AA 24 ECONODE
Location ID: 427153



Photo 7 – South Separators



Photo 8 – South Headers

Inspection Photos
Location Name: Wells Ranch AA 24 ECONODE
Location ID: 427153



Photo 9 – Maintenance Tank



Photo 10 – North Separators

Inspection Photos
Location Name: Wells Ranch AA 24 ECONODE
Location ID: 427153



Energy and Carbon Management Commission
40.47096, -104.39282, 4765.4ft
01/24/2024 12:02:29

Photo 11 – Generators



Energy and Carbon Management Commission
40.47138, -104.39286, 4763.5ft
01/24/2024 12:02:48

Photo 12 – North Headers

Inspection Photos
Location Name: Wells Ranch AA 24 ECONODE
Location ID: 427153



Photo 13 – Flare



Photo 14 – Instrumental Air Unit

Inspection Photos
Location Name: Wells Ranch AA 24 ECONODE
Location ID: 427153



Photo 15 – Compressor



Photo 16 – Unused Secondary Containment