

**Inspection Photos**  
**Location Name: Wells Ranch AA 24-64HN PAD**  
**Location ID: 428367**



Energy and Carbon Management Commission  
40.46758, -104.39429, 4735.9ft  
01/24/2024 12:08:17

**Photo 1 – West Gas Lift Injection Meter House**



Energy and Carbon Management Commission  
40.46694, -104.39417, 4781.4ft  
01/24/2024 12:08:51

**Photo 2 – West Wellheads**

**Inspection Photos**  
**Location Name: Wells Ranch AA 24-64HN PAD**  
**Location ID: 428367**



**Photo 3 – Wellhead Sign**



**Photo 4 – East Gas Lift Injection Meter House**



**Inspection Photos**  
**Location Name: Wells Ranch AA 24-64HN PAD**  
**Location ID: 428367**



**Photo 5 – 24-64HN Wellsite**



**Photo 6 – Wellhead Sign**

**Inspection Photos**  
**Location Name: Wells Ranch AA 24-64HN PAD**  
**Location ID: 428367**



**Photo 7 – Unused Stairs and Automation Equipment**



**Photo 8 – East Wellheads**



**Inspection Photos**  
**Location Name: Wells Ranch AA 24-64HN PAD**  
**Location ID: 428367**



Energy and Carbon Management Commission  
40.46715, -104.39378, 4766.4ft  
01/24/2024 12:10:14

**Photo 9 – Wellhead Sign**