

**Inspection Photos**  
**Location Name: Wells Ranch AF 08-08 ECONODE**  
**Location ID: 449294**



**Photo 1 – Unused Stairs on West side of Location**



**Photo 2 – Methanol Day Tank at Entrance – Tumbleweed Debris and Wildlife Netting**

**Inspection Photos**  
**Location Name: Wells Ranch AF 08-08 ECONODE**  
**Location ID: 449294**



**Photo 3 – Bulk Tank**



**Photo 4 – Gas Meters**



**Inspection Photos**  
**Location Name: Wells Ranch AF 08-08 ECONODE**  
**Location ID: 449294**



**Photo 5 – Separators**



**Photo 6 – Separators**

**Inspection Photos**  
**Location Name: Wells Ranch AF 08-08 ECONODE**  
**Location ID: 449294**



**Photo 7 – Maintenance Tanks**



**Photo 8 – Compressor**



**Inspection Photos**  
**Location Name: Wells Ranch AF 08-08 ECONODE**  
**Location ID: 449294**



**Photo 9 – Production Equipment**



**Photo 10 – Generators**

**Inspection Photos**  
**Location Name: Wells Ranch AF 08-08 ECONODE**  
**Location ID: 449294**



**Photo 11 – Instrumental Air Unit**



**Photo 12 – ECDs**

**Inspection Photos**  
**Location Name: Wells Ranch AF 08-08 ECONODE**  
**Location ID: 449294**



Energy and Carbon Management Commission  
40.41388, -104.33886, 4617.4ft  
01/24/2024 12:52:59

**Photo 13 – LACT Unit**