

Interim Reclamation and Stormwater Inspection

Date: 1/19/24

Operator: Bonanza Creek Energy Operating
Company LLC - 8960

Location ID: 471040

Inspection Document #: 713900289

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Antelope O-31
Location ID: 471040



Photo 1. The photo was taken at the well location facing West. The photo illustrates the operator location sign.



Photo 2. The photo was taken at the well location facing South. The photo illustrates the interim areas are dominated by Russian thistle.

Inspection Photos
Location Name: Antelope O-31
Location ID: 471040




Photo 3. The photo was taken at the well location facing North.
Refer to the comment for photo 2.



Photo 4. The photo was taken at the well location facing West.
Refer to the comment for photo 2.

Inspection Photos
Location Name: Antelope O-31
Location ID: 471040



Photo 5. The photo was taken at the well location facing South.
Refer to the comment for photo 2.



Photo 6. The photo was taken at the well location facing East.
Refer to the comment for photo 2.