

Final Reclamation and Stormwater Inspection

Date: 1/19/24

Operator: Bonanza Creek Energy Operating
Company LLC - 8960

Location ID: 423761

Inspection Document #: 713900297

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Antelope 24-20
Location ID: 423761



Photo 1. The photo was taken from the well location facing East. The photo illustrates the active road by the location as well as recruitment of Russian thistle.



Photo 2. The photo was taken from the well location facing Southwest. Refer to the comment for photo 1.

Inspection Photos
Location Name: Antelope 24-20
Location ID: 423761



Photo 3. The photo was taken from the well location facing West. The photo illustrates some desirable vegetation germination but dominance of russian thistle across the location.



Photo 4. The photo was taken from the well location facing West. Refer to the comment for photo 3.

Inspection Photos
Location Name: Antelope 24-20
Location ID: 423761



Photo 5. The photo was taken from the well location facing South. Refer to the comment for photo 3



Photo 6. The reference photo was taken near the well location facing North.