

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE MF07C-4 C04 696 Pad

Location # 311638



Jan 25, 2024 at 1:52:16 PM



Jan 25, 2024 at 1:59:37 PM

Photo # 4087 From entrance to location

Photo # 4088 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE MF07C-4 C04 696 Pad

Location # 311638



Photo # 4089 Location/blowdown tank



Photo # 4090 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE MF07C-4 C04 696 Pad

Location # 311638



Jan 25, 2024 at 2:02:55 PM



Jan 25, 2024 at 2:04:42 PM

Photo # 4091 Location

Photo # 4092 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE MF07C-4 C04 696 Pad

Location # 311638



Photo # 4093 Location



Photo # 4094 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE MF07C-4 C04 696 Pad

Location # 311638



Photo # 4095 Location



Photo # 4096 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE MF07C-4 C04 696 Pad

Location # 311638



Jan 25, 2024 at 1:52:58 PM



Jan 25, 2024 at 1:53:04 PM

Photo # 4097 Holes/safety issue/personnel & wildlife hazard

Photo # 4098 Holes/safety issue/personnel & wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE MF07C-4 C04 696 Pad

Location # 311638



Photo # 4099 Holes/safety issue/personnel & wildlife hazard



Photo # 4100 Holes/safety issue/personnel & wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE MF07C-4 C04 696 Pad

Location # 311638



Photo # 4101 Holes/safety issue/personnel & wildlife hazard



Photo # 4102 Holes/safety issue/personnel & wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE MF07C-4 C04 696 Pad

Location # 311638



Photo # 4103 Hole/safety issue/personnel & wildlife hazard



Photo # 4104 Hole/safety issue/personnel & wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE MF07C-4 C04 696 Pad

Location # 311638



Photo # 4105 Hole/safety issue/personnel & wildlife hazard



Photo # 4106 Holes/safety issue/personnel & wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE MF07C-4 C04 696 Pad

Location # 311638



Photo # 4107 Holes/safety issue/personnel & wildlife hazard



Photo # 4108 Holes/safety issue/personnel & wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE MF07C-4 C04 696 Pad

Location # 311638



Photo # 4109 Open valve leaking gas on the MF04B-3 wellhead



Photo # 4110 Open valve leaking gas on the MF04B-3 wellhead

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE MF07C-4 C04 696 Pad

Location # 311638



Photo # 4111 Open valve leaking gas on the MF07A-4 wellhead



Photo # 4112 Open valve leaking gas on the MF07A-4 wellhead

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE MF07C-4 C04 696 Pad

Location # 311638



Photo # 4113 Debris



Photo # 4114 Debris



Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE MF07C-4 C04 696 Pad

Location # 311638



Photo # 4115 Improperly marked deadman



Photo # 4116 Improperly marked deadman

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE MF07C-4 C04 696 Pad

Location # 311638



Photo # 4117 Tank containment damaged/buckling



Photo # 4118 Tank containment damaged/buckling

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE MF07C-4 C04 696 Pad

Location # 311638



Photo # 4119 Tank containment damaged/buckling