

## Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF06D L29 595 Pad

Location #: 335607



Photo # 4037 From entrance to location



Photo # 4038 From entrance to location

# Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF06D L29 595 Pad

Location #: 335607



Photo # 4039 Location

Photo # 4040 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF06D L29 595 Pad

Location #: 335607



Photo # 4041 Location



Photo # 4042 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF06D L29 595 Pad

Location #: 335607



Photo # 4043 Location




Photo # 4044 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF06D L29 595 Pad

Location #: 335607



Photo # 4045 Location



Photo # 4046 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF06D L29 595 Pad

Location #: 335607



Photo # 4047 Location




Photo # 4048 Labeling on blowdown tank missing required info & has inaccurate info

## Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF06D L29 595 Pad

Location #: 335607



**Photo # 4049 Hole in ground near sales gas meter house/safety issue/wildlife & personnel hazard**



**Photo # 4050 Hole in ground near sales gas meter house/safety issue/wildlife & personnel hazard**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF06D L29 595 Pad

Location #: 335607



**Photo # 4051 Hole in ground near sales gas meter house/safety issue/wildlife & personnel hazard**



**Photo # 4052 Hole in ground near sales gas meter house/safety issue/wildlife & personnel hazard**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE EF06D L29 595 Pad

Location #: 335607



**Photo # 4053 Hole in ground near sales gas meter house/safety issue/wildlife & personnel hazard**



**Photo # 4054**