

Final Reclamation Inspection

January 25th, 2024

Operator: Simcoe LLC - 10749

Location ID: 306900

Inspection Document #: 714000352

La Plata County, CO

Township: NWNE 3 34N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Keating 2
Location ID: 306900



Photo 1. View of the disturbance from the entrance facing center.



Inspection Photos
Location Name: Keating 2
Location ID: 306900



Photo 2. View of stained soil around muffler.

Inspection Photos
Location Name: Keating 2
Location ID: 306900



Photo 3. View of southern interim reclamation area facing southeast. Interim vegetation was not fully assessed due to snowy conditions.