

Inspection Photos
HORTH #1 FLOWLINE SPILL
Spill ID 485897



Photo 1 – Open excavation



Photo 2 - Open excavation

Inspection Photos
HORTH #1 FLOWLINE SPILL
Spill ID 485897



Photo 3 – Open excavation



Photo 4 - Open excavation/fencing



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
HORTH #1 FLOWLINE SPILL
Spill ID 485897



Photo 5 – Soils pile



Photo 6 - Wellhead

Inspection Photos
HORTH #1 FLOWLINE SPILL
Spill ID 485897



Photo 7 – Stained soil



Photo 8 - Stained soil

