

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/2SESW

Location ID: 334869

Date: 1/29/2024



Jan 29, 2024 at 14:03:43
Parachute CO 81635
United States

Wellheads – Photo #08887



Jan 29, 2024 at 14:05:51
Parachute CO 81635
United States

Separators – Photo #08890

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/2SESW

Location ID: 334869

Date: 1/29/2024



Tank Battery – Photo #08889



Lack of Stabilization – Photo #08888



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/2SESW

Location ID: 334869

Date: 1/29/2024



Lack of Stabilization – Photo #08891