

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403655300

Date Received:  
01/15/2024

## FIR RESOLUTION FORM

Overall Status: CAC

### CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10633

Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Luke Kelly

970-939-6353

lkelly@civiresources.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 690011944

Inspection Date: 12/07/2023

FIR Submit Date: 12/07/2023

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: CRESTONE PEAK RESOURCES OPERATING LLC

Company Number: 10633

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

### LOCATION - Location ID: 432679

Location Name: Devore Number: 34H-A366 County: WELD

Qtrqr: NENE Sec: 34 Twp: 3N Range: 66W Meridian: 6

Latitude: 40.188220 Longitude: -104.758710

### FACILITY - API Number: 05-123- -00 Facility ID: 432682

Facility Name: Devore Number: 1A-34H

Qtrqr: NENE Sec: 34 Twp: 3N Range: 66W Meridian: 6

Latitude: 40.188220 Longitude: -104.758710

### CORRECTIVE ACTIONS:

1 ☒ CA# 188969

Corrective Action: Install sign to comply with Rule 605.g.

Date: 01/15/2024

Response: CA COMPLETED

Date of Completion: 01/15/2024

Operator  
Comment:

Operator has updated/replaced the signage to comply with Rule 605.g.

COGCC Decision: Approved pending re-inspection



Install sign to comply with Rule 605.g.

Date of Completion: 01/15/2024

Operator has updated/replaced the signage to comply with Rule 605.g. Additional signage is in process and will be installed when received.

Approved pending re-inspection

--

CA follow-up has been completed for this location.
--

Signed: \_\_\_\_\_

Date: 1/15/2024 6:35:28 PM

403655300	FIR RESOLUTION SUBMITTED
403655301	Inspection Resolution Report

Page 2 of 2