

Inspection Photos
Location Name: Hazel McHale 4
Location ID: 318373



Photo 1 Location.



Photo 2 Location.

Inspection Photos
Location Name: Hazel McHale 4
Location ID: 318373



Photo 3 Tall dead vegetation around the WH.



Photo 4 WH sign lying on the ground and needs to be rehung.

Inspection Photos
Location Name: Hazel McHale 4
Location ID: 318373



Photo 5 Tall dead vegetation around the pump jack and ancillary equip.



Photo 6 Tall dead vegetation around the ancillary equip.

Inspection Photos
Location Name: Hazel McHale 4
Location ID: 318373



Photo 7 Tall dead vegetation around the ancillary equip.