

# Final Reclamation Inspection

January 26, 2024

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 321507

Inspection Document #: 697505089

Broomfield County, CO

Chris Binschus  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: GREEN-61S68W 17SESE  
Location ID: 321507



**Photo 1.** Photo taken from the tank battery location, facing East. Photo illustrates 5'-6' unmanaged weeds which are not reflective of reference areas.



**Photo 2.** Photo taken from the north well location access road, facing South. Photo illustrates unmanaged weeds along the access road.



Inspection Photos  
Location Name: GREEN-61S68W 17SESE  
Location ID: 321507



**Photo 3.** Photo taken from a portion of the access road, facing East. Reference area vegetation is below the red-dashed line; the weedy access road above the red-dashed



Inspection Photos  
Location Name: GREEN-61S68W 17SESE  
Location ID: 321507



**Photo 4.** Google Earth aerial imagery from 9/21/2021. There has been some land use change along a portion of the access road that is not the responsibility of the Operator. Operator is responsible for the red outlined area.