

Final Reclamation Inspection

January 30th, 2024

Operator: Simcoe LLC - 10749

Location ID: 334242

Inspection Document #: 714000371

La Plata County, CO

Township: NESE 8 34N 7W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Emma McCarty A1, A3
Location ID: 334242



Photo 1. View of the disturbance from the entrance facing center.



Inspection Photos

Location Name: Emma McCarty A1, A3

Location ID: 334242



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Unused oil and gas fence equipment on location.

API #: 067-07856, 09334

Inspection Photos
Location Name: Emma McCarty A1, A3
Location ID: 334242

1/30/24
+37.202894,-107.626234
217° SW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Surface owner trailers, cars and boat stored on the southern edge of the disturbance.

API #: 067-07856, 09334

Inspection Photos

Location Name: Emma McCarty A1, A3

Location ID: 334242



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Gully erosion forming downhill of current stormwater BMPs in the southern interim reclamation area.

API #: 067-07856, 09334

Inspection Photos

Location Name: Emma McCarty A1, A3

Location ID: 334242



Photo 5. Rill erosion forming along the access road at the access point of the disturbance.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07856, 09334

Inspection Photos
Location Name: Emma McCarty A1, A3
Location ID: 334242

1/30/24
+37.203509,-107.626466
341° N



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 6. Reference area comprised of juniper and sagebrush.

API #: 067-07856, 09334