

Final Reclamation Inspection

January 30th, 2024

Operator: Simcoe LLC - 10749

Location ID: 306905

Inspection Document #: 714000372

La Plata County, CO

Township: SWSW 9 34N 7W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: French 01-9U 2R
Location ID: 306905

1/30/24
+37.202165,-107.619169
197° S



Photo 1. View of the disturbance from the entrance facing center.



Inspection Photos
Location Name: French 01-9U 2R
Location ID: 306905



Photo 2. Patches of musk thistle observed through the interim reclamation.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09019

Inspection Photos
Location Name: French 01-9U 2R
Location ID: 306905



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. View of additional musk thistle patches observed along the access road.

API #: 067-09019

Inspection Photos
Location Name: French 01-9U 2R
Location ID: 306905



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Reference area comprised of crested wheatgrass, sagebrush and rabbitbrush.

API #: 067-09019