

Final Reclamation Inspection

January 30th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325535

Inspection Document #: 714000375

La Plata County, CO

Township: NWNE 16 34N 7W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Couch 01-16U 1
Location ID: 325535

1/30/24
+37.196105,-107.609441
109° E



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 1. View of the northern interim reclamation area facing east.

API #: 067-06567

Inspection Photos

Location Name: Couch 01-16U 1

Location ID: 325535



Photo 2. View of weedy kochia debris and jointed goatgrass observed in the western interim reclamation area.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-06567

Inspection Photos
Location Name: Couch 01-16U 1
Location ID: 325535

1/30/24
+37.195753,-107.609143
75° E



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Reference area is an irrigated grass field in dormant stage.

API #: 067-06567