

Final Reclamation Inspection

January 30th, 2024

Operator: Simcoe LLC - 10749

Location ID: 334280

Inspection Document #: 714000378

La Plata County, CO

Township: NWSE 17 34N 7W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: State CD 1,3
Location ID: 334280




Photo 1. View of the disturbance from the entrance facing center.

Inspection Photos
Location Name: State CD 1,3
Location ID: 334280



Photo 2. Stained soils remain at well head #1.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07852, 09499

Inspection Photos
Location Name: State CD 1,3
Location ID: 334280



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. View of musk thistle observed in the southeastern interim reclamation area.

API #: 067-07852, 09499

1/30/24
+37.188456,-107.631575
228° SW



Photo 4. View of surface owner haul truck that remains stored on location.

Inspection Photos
Location Name: State CD 1,3
Location ID: 334280



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Reference area comprised of sagebrush and juniper.

API #: 067-07852, 09499