

## Inspection Photos


Operator: Darrah Oil Company LLC (10713)

Lease: Champlin 205 Amoco A-2

Facility ID/API, 207461 / 05-017-06396




1. Lease sign by well




2. Inadequate Berms



**Inspection Photos**  
**Operator: Darrah Oil Company LLC (10713)**  
**Lease: Champlin 205 Amoco A-1**  
**Facility ID/API, 207313 / 05-017-06248**




**3. HHT, VHT, FWKO**



**4. Tank battery**



**Inspection Photos**  
**Operator: Darrah Oil Company LLC (10713)**  
**Lease: Champlin 205 Amoco A-1**  
**Facility ID/API, 207313 / 05-017-06248**



**5. Inadequate berms around tank battery**



**6. Inadequate berms around tank battery**

## Inspection Photos

Operator: Darrah Oil Company LLC (10713)

Lease: Champlin 205 Amoco A-1

Facility ID/API, 207313 / 05-017-06248



5. Inadequate berms around production equipment

