


Inspection Photos
Operator: Darrah Oil Company LLC (10713)
Lease: Larsen 23-11
Facility ID/API, 207489 / 05-017-06424




1. Lease sign by tanks




2. Pumping Unit

Inspection Photos
Operator: Darrah Oil Company LLC (10713)
Lease: Larsen 23-11
Facility ID/API, 207489 / 05-017-06424




3. Tank Battery




4. Free Water Knock Out

Inspection Photos
Operator: Darrah Oil Company LLC (10713)
Lease: Larsen 23-11
Facility ID/API, 207489 / 05-017-06424



5. Failed Berm



5. Erosion on lease road