

# Final Reclamation Inspection

February 7th, 2024

Operator: Simcoe LLC - 10749

Location ID: 326331

Inspection Document #: 714000397

La Plata County, CO

Township: SESE 20 34N 7W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Knight D 1  
Location ID: 326331




Photo 1. View of the disturbance from the entrance facing center.



Inspection Photos  
Location Name: Knight D 1  
Location ID: 326331

2/7/24  
+37.172155,-107.627263  
35° NE



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** Hay CA from previous inspection has been addressed/resolved.

API #: 067-07850



Inspection Photos  
Location Name: Knight D 1  
Location ID: 326331



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** Berm CA from previous inspection has been addressed/resolved.

API #: 067-07850



Inspection Photos  
Location Name: Knight D 1  
Location ID: 326331



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Sound panel identified in previous inspection remains stored on location.

API #: 067-07850



Inspection Photos  
Location Name: Knight D 1  
Location ID: 326331



2/7/24  
+37.172155, -107.627263  
22° N

**Photo 5.** Unused oil and gas equipment on location.




**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-07850



Inspection Photos  
Location Name: Knight D 1  
Location ID: 326331



**Photo 6.** View of gully erosion forming in the western interim reclamation area, with old wattle stakes observed in the ground.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-07850