

Inspection Photos

2/5/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335780

Inspection Doc: 696205600

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335780



Photo 1: Working pad surface lacks stabilization; BMPs to minimize erosion, degradation and sediment transport missing or insufficient.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335780



Photo 2: Working pad surface lacks stabilization; BMPs to minimize erosion, degradation and sediment transport missing or insufficient.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335780



Photo 3: Trash/Debris at tank battery.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources



February 5, 2024



February 5, 2024



February 5, 2024

Photo 4: Lines at tanks lack cap/plug.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335780



Photo 5: Photos taken from the interim areas on the east end of the Location. Gravel does not appear to have been removed from these areas. Vegetation establishment does not appear to be uniform.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources