

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/17SWSE

Location ID: 335424

Date: 2/5/2024



Location Entrance – Photo #09137



Wellheads – Photo #09138

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/17SWSE

Location ID: 335424

Date: 2/5/2024



Separators – Photo #09142



Tank Battery – Photo #09141

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/17SWSE

Location ID: 335424

Date: 2/5/2024



Lack of Stabilization – Photo #09140



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #09143**