

Inspection Photos

Loc: 321584

Operator: CITATION OIL & GAS CORP

Inspection Date: 2/7/2024

County: CHEYENNE



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast toward the wellsite location.



Inspection Photos



Photo 2. South side of the location facing east. This are to the right of the solar panel has ne vegetation growth and needs to be reclaimed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:321584 | Date: 2/7/2024

Inspection Photos



Photo 3. Facing northeast toward the well. There is an unmarked/unused pipe riser shown at red arrow.



Inspection Photos



Photo 4. The pipe riser is not capped and is is unused which needs to be removed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:321584 | Date: 2/7/2024

Inspection Photos



Photo 5. Facing toward the wellhead which has not produced for a very long time. There is no well sign posted at the wellhead.



Inspection Photos



Photo 6. Facing southeast at the location. Unused areas of the location are not reclaimed and consists of undesirable weeds.



Inspection Photos



Photo 7. Southwest side of the location facing northeast. There is a pipeline cellar with the lid off laying on the ground.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:321584 | Date: 2/7/2024