

Interim and Stormwater Inspection

January 30, 2023

Operator: Kerr McGee Oil & Gas- #47120

Location ID: 332254

Inspection Document #: 709400779

Weld County, CO

NESW Section 20 T2N R65W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Palmer 11-20
Location ID: 332254



Photo 1. Photo taken of location sign, facing south.



Photo 2. Photo taken of wires not leading to equipment. Photo taken facing north.

Inspection Photos
Location Name: Palmer 11-20
Location ID: 332254



Photo 3. Photo taken of location sign at tank battery, facing south.



Photo 4. Photo taken of tank battery on pad. Photo taken facing southeast.



Inspection Photos
Location Name: Palmer 11-20
Location ID: 332254



Photo 5. Photo taken of weeds (kochia & russian thistle). Photo taken facing north.



Photo 6. Photo taken of weeds (russian thistle & canada thistle) on site. Photo taken facing southeast.

Inspection Photos
Location Name: Palmer 11-20
Location ID: 332254



Photo 7. Photo taken of weeds (kochia & russian thistle) on site. Photo taken facing north.



Photo 8. Photo taken of weeds (kochia & russian thistle) on pad. Photo taken facing north.