

Inspection Photos

Loc: 380428

Operator: FOUNDATION ENERGY MANAGEMENT LLC

Inspection Date: 2/7/2024

County: CHEYENNE



Inspection Photos



Photo 1. Facing east toward the access road which has mostly revegetated.



Inspection Photos



Photo 2. Facing east toward the location. This area approximately 50'x50' has no vegetation and soils appear impacted from historic release at the wellhead.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:380428 | Date: 2/7/2024

Inspection Photos



Photo 3. There is equipment parts that remain at the location that need to be removed.



Inspection Photos



February 7, 2024
+38.928692,-102.989944

Photo 4. Center of the location facing north. There are undesirable weeds and areas of bare soil.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:380428 | Date: 2/7/2024

Inspection Photos



Photo 5. Center of the location facing south. There are undesirable weeds and areas of bare soil.



Inspection Photos



Photo 6. Facing toward the southeast side of the location. Soils are bare of vegetation and there is a mound of soil in this area.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:380428 | Date: 2/7/2024

Inspection Photos



Photo 7. Facing northeast at the south side of the location. There are bare soils in this area where the berms of the tanks may have previously been. Bare soils appear impacted preventing vegetation growth.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:380428 | Date: 2/7/2024

Inspection Photos



Photo 8. Facing south toward the surrounding undisturbed pasture.

