

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Location Name: Antelope 24-20

Loc ID: 423761

Inspection: 713900297




Exhibit A

CA: This location does not comply with Rule 1004. Reclamation activities, namely seeding, were noted on Form 4 Sundry Notice Doc#403129032 to have occurred on 08/01/2022 and though there is some germination of desirable species the well location is dominated by Russian thistle. The tank battery location serviced multiple wells and remains active and will be linked to well API #'s 123-33713 and 123-33715. Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management. The corrective date is the date the location was observed out of compliance, as it should be in compliance at all times.

CA Resolution: Operator has reported that the location has been appropriately mowed, seeded, and stabilized with straw mulch to comply with Rule 1004.