

Inspection Photos
Location Name: THISTLE DOWN B/31-31D
Location #: 302546



Photo #1

Thistle Down B 31-31D (123-30795) Wellsite
Plugged & Abandoned | PA
Cut / Capped
~ 55 yds.



Photo #2

Thistle Down B 31-30D, B 31-31D,
Gemini B 31-3, B 31-19,
Gemini – UPRR B31-4, B31-5, B31-6
Battery site
Abandoned: ALL Equipment Removed

