

Inspection Photos

Location Name: GEMINI-UPRR-65N64W/31SWNW

Location #: 326823



Photo #1

Gemini-UPRR B31-5 (123-13722) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 200 yds.



Photo #2

Thistle Down B 31-30D, B 31-31D,

Gemini B 31-3, B 31-19,

Gemini – UPRR B31-4, B31-5, B31-6

Battery site

Abandoned: ALL Equipment Removed



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources