

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/29SENE

Location ID: 335328

Date: 2/8/2024



Wellheads – Photo #09161




Separators – Photo #09155

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/29SENE

Location ID: 335328

Date: 2/8/2024



Tank Battery – Photo #09156




Weathered Sign – Photo #09162

Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/29SENE

Location ID: 335328

Date: 2/8/2024



Weathered Sign – Photo #09163



Weathered Sign – Photo #09164

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/29SENE

Location ID: 335328

Date: 2/8/2024



Weathered Sign – Photo #09157

