

Inspection Photos
Location Name: Hunt 08-60-6A PAD
Location ID: 454627



Photo 1 – 31-30-10 Wellhead



Photo 2 – Wellhead Sign – Emergency Number

Inspection Photos
Location Name: Hunt 08-60-6A PAD
Location ID: 454627



Photo 3 – 31-30-9 Wellhead



Photo 4 – Wellhead Sign – Emergency Number

Inspection Photos
Location Name: Hunt 08-60-6A PAD
Location ID: 454627




Photo 5 – 31-30-7 Wellhead



Photo 6 – Wellhead Sign – Emergency Number

Inspection Photos
Location Name: Hunt 08-60-6A PAD
Location ID: 454627



Photo 7 – Tank Battery



Photo 8 – Separators

Inspection Photos
Location Name: Hunt 08-60-6A PAD
Location ID: 454627



Photo 9 –Gas Injection Meter House



Photo 10 – Compressor



Inspection Photos
Location Name: Hunt 08-60-6A PAD
Location ID: 454627



Photo 11 – Sign at Gas Meter




Photo 12 – Gas Meter Calibration Cards

Inspection Photos
Location Name: Hunt 08-60-6A PAD
Location ID: 454627



Photo 13 – Electrical Equipment



Photo 14 – VRU



Inspection Photos
Location Name: Hunt 08-60-6A PAD
Location ID: 454627



Photo 15 – ECD



Photo 16 – LACT

Inspection Photos
Location Name: Hunt 08-60-6A PAD
Location ID: 454627



Photo 17 – Tank Battery and VRT



Photo 18 – Sign at Entrance

