

Inspection Photos
Location Name: Shable Fed LB 33-78HN PAD
Location ID: 431817



Photo 1 – Gas Meter Houses



Photo 2 – Separators

Inspection Photos
Location Name: Shable Fed LB 33-78HN PAD
Location ID: 431817



Photo 3 – ECDs



Photo 4 – Tank Battery Sign

Inspection Photos
Location Name: Shable Fed LB 33-78HN PAD
Location ID: 431817



Photo 5 – Tank Battery



Photo 6 – Tank Battery



Inspection Photos
Location Name: Shable Fed LB 33-78HN PAD
Location ID: 431817



Photo 7 – Tank Battery Sign



Photo 8 – 33-78HN Wellsite

Inspection Photos
Location Name: Shable Fed LB 33-78HN PAD
Location ID: 431817



Photo 9 – Wellhead



Photo 10 – 32-68HN Wellsite

Inspection Photos
Location Name: Shable Fed LB 33-78HN PAD
Location ID: 431817



Photo 11 – Wellhead Sign



Photo 12 – 32-68HN Wellhead

Inspection Photos
Location Name: Shable Fed LB 33-78HN PAD
Location ID: 431817



Photo 13 – Black Container missing Label at 33-78HN Wellsite



Photo 14 – Unused Secondary Containment at 32-68HN Wellsite