

Inspection Photos
Location Name: Wells Ranch USX AE 31-12
Location ID: 310024



Energy and Carbon Management Commission
40.44098, -104.37368, 4632.7ft
02/07/2024 12:55:38



Energy and Carbon Management Commission
40.44099, -104.37368, 4633.9ft
02/07/2024 12:55:42

Photo 1 – Wellhead – Tumbleweeds

Photo 2 – Wellhead Sign

Inspection Photos
Location Name: Wells Ranch USX AE 31-12
Location ID: 310024



Photo 3 – Unmarked Riser

Photo 4 – Wellhead Tags