WELL SITE INSPECTION FORM
(DRILLING AND PLUGGING)

Well Name Haggerty 1 API Number 05 - (087 - 5812)
Operator Cimarron Western Dr Permit # 55 —
Location NWNE 10-2N-58W County Morgan
Field _____ Inspector EBB

99999999

AL/PA/DA Inspection Results: Well Status:
Pass(Y) ✓ Fail(N)____ Date 12/1/91 ND____ DG____ WO____ PR____ SI____ TA____

==========

Date of Inspection Before/During Drilling_____

Surf. Csg. Size_____ Setting Depth_____ Cmt. Vol._____ WOC time_____
Consistent with APD casing Program? YES_____ NO____ Returns_____
Rig_____ BOP'S_____ Stage Tool Depth_____ Cmt. Vol._____

Date of Inspection Before/During/After Completion_____

Prod. Csg. Set?_____ Completion Rig/Activity_____
Drilling Pits: Closed____ Open____ Wellhead Installed: ____ Sign: Yes____ No____
Tank ID: Yes___ No___ N/A___ Skim Tank/Pit: _____ Prod. Tanks: ( ) _____BBLS
Equipment_____ Meter Run: Yes_____ No_____
Bradenhead Press:_____ Fluid: No_____ Yes_____ Type_____ Well Cat. _____

AL/PA/DA Inspection

Date Plugged:_____ Date Permit Expired:_____
Hole Plugged: Yes____ No____ Pits Backfilled: Yes____ No____
Material Buried: Yes____ No____ N/A____ Site Clean: Yes____ No____
Bond Release OK: Yes____ No____ Fed____ Hole Marker: Yes____ No____

Date of Safety/Status Inspection_____

Comments:_____

00080135

Violations: Yes_____ No_____ Notice Sent: Yes_____ No____ Date Sent:_____