

Inspection Photos

Operator: GREENLEAF ENVIRONMENTAL SERVICES LLC - 10628

Location Name: GREENLEAF DISPOSAL #1

Location ID: 312454 API #: 05-077-08255

Inspection Date: 2/12/2024 Inspection Doc#: 693806715



Injection wellhead with sign.



Pump housing and used filter storage

