

Inspection Photos

Location Name: OCOMA B-65N64W/31SESE

Location #: 305098



Photo #1

Ocoma B 31-23 (123-22440) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 85 yds.



Photo #2

Ocoma UPRR Lease B31-15, B31-10,

Ocoma B 31-23

Battery site

Abandoned: ALL Equipment Removed



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources