

## Inspection Photos

Location Name: OCOMA UPRR LEASE-65N64W/31NWSE

Location #: 323703



**Photo #1**

**Ocoma UPRR Lease B31-10 (123-13394) Wellsite**

**Plugged & Abandoned | PA**

*Cut / Capped*

*~ 130 yds.*



**Photo #2**

**Ocoma UPRR Lease B31-15, B31-10,**

**Ocoma B 31-23**

**Battery site**

***Abandoned: ALL Equipment Removed***



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources