

Inspection Photos
Location Name: OCOMA-65N64W/31NESE
Location #: 323674



Photo #1
Ocoma B31-9 (123-13353) Wellsite
Plugged & Abandoned | PA
Cut / Capped
~ 30 yds.



Photo #2
Ocoma B31-16, Ocoma B31-9
Battery site
Abandoned: ALL Equipment Removed

