

Inspection Photos

Loc: 477611

Operator: KODA EXPLORATION LLC

Inspection Date: 2/13/2024

County: LINCOLN



Inspection Photos



Photo 1. Facing west at the access road off the county road. The fence needs to be reinstalled back to the original position. The gravel needs to be removed and road reclaimed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:477611 | Date: 2/13/2024

Inspection Photos



Photo 2. Facing west toward the location which is fenced off.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:477611 | Date: 2/13/2024

Inspection Photos



Photo 3. Facing west at the center of the location. The location has been mowed but there is mostly undesirable weed cover and perennial vegetation has not adequately established.



Inspection Photos



Photo 4. Facing north at the center of the location.



Inspection Photos



Photo 5. Facing north at the center of the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:477611 | Date: 2/13/2024

Inspection Photos



Photo 6. View of ground cover shows mostly undesirable weeds (Kochia).

