

Inspection Photos

Loc: 472992

Operator: KODA EXPLORATION LLC

Inspection Date: 2/13/2024

County: LINCOLN



Inspection Photos



Photo 1. Facing east at the access road off the county road. The fence needs to be reinstalled back to the original position. The gravel needs to be removed and road reclaimed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:472992 | Date: 2/13/2024