

Final Reclamation and Stormwater Inspection

Date: 2/9/24

Operator: Vista Operating Inc. - 100128

Location ID: 317410

Inspection Document #: 713900357

Washington County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Dapper-Small 23-35
Location ID: 317410



Photo 1. The photo was taken along the access road facing East. The photo illustrates the access road is still in use for an active well.



Photo 2. The photo was taken at the well location facing North. The photo illustrates the well location is dominated by Sand dropseed and grama and has been actively grazed.

Inspection Photos

Location Name: Dapper-Small 23-35

Location ID: 317410



Photo 3. The photo was taken at the well location facing East.
Refer to the comment for photo 2.



Photo 4. The photo was taken at the well location facing South.
Refer to the comment for photo 2.

Inspection Photos
Location Name: Dapper-Small 23-35
Location ID: 317410



Photo 5. The photo was taken at the well location facing West. Refer to the comment for photo 2.



Photo 6. The reference photo was taken near the well location facing Northwest. The photo illustrates reference areas are dominated by Sand dropseed, Grama, Horseweed and Yucca.