

Final Reclamation Inspection

February 13th, 2024

Operator: Simcoe LLC - 10749

Location ID: 333568

Inspection Document #: 714000424

La Plata County, CO

Township: SENW 31 34N 7W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Fairfield Farms 1, 3
Location ID: 333568

2/13/24
+37.150074,-107.653066
327° NW



Photo 1. View of the disturbance from the entrance facing center.



Inspection Photos
Location Name: Fairfield Farms 3
Location ID: 333568



2/13/24
+37,150589,-107.653667
151° SE

Photo 2. View of the western interim reclamation area facing southeast. Interim has patches of crested wheatgrass establishing.



Inspection Photos
Location Name: Fairfield Farms 3
Location ID: 333568



Photo 3. Produced water sign does not have tank capacity listed.



Inspection Photos
Location Name: Fairfield Farms 3
Location ID: 333568



Photo 4. View of unused trailer stored on location.

Inspection Photos
Location Name: Fairfield Farms 3
Location ID: 333568

2/13/24
+37.150228,-107.653111
291° W

