

Inspection Photos
Location Name: Miller 23-17
Location ID: 336436



Photo 1 Location.



Photo 2 WH sign.

Inspection Photos
Location Name: Miller 23-17
Location ID: 336436



Photo 3 WH.



Photo 4 TB signs.



Inspection Photos
Location Name: Miller 23-17
Location ID: 336436



Photo 5 TB.



Photo 6 Gas Meter Run.

Inspection Photos
Location Name: Miller 23-17
Location ID: 336436



Photo 7 Horizontal Heated Separator.



Photo 8 ECD.