

Inspection Photos
Location Name: Hunt 8-60-17B PAD
Location ID: 457475



Photo 1 – Tank Battery



Photo 2 – LACT

Inspection Photos
Location Name: Hunt 8-60-17B PAD
Location ID: 457475



Photo 3 – ECDs



Photo 4 – Electrical and Automation Equipment

Inspection Photos
Location Name: Hunt 8-60-17B PAD
Location ID: 457475



Photo 5 – Instrumental Air Units



Photo 6 – Gas Meter House



Inspection Photos
Location Name: Hunt 8-60-17B PAD
Location ID: 457475



Photo 7 – Compressors



Photo 8 – Wildlife Netting in disrepair

Inspection Photos
Location Name: Hunt 8-60-17B PAD
Location ID: 457475



Photo 9 – Separators



Photo 10 – Tank Battery

Inspection Photos
Location Name: Hunt 8-60-17B PAD
Location ID: 457475



Photo 11 – Separators



Photo 12 – 24-Hour Emergency Number

Inspection Photos
Location Name: Hunt 8-60-17B PAD
Location ID: 457475



Photo 13 – Sign at Entrance

