

Inspection Photos  
Location Name: Hunt 8-60-17A PAD  
Location ID: 457131



Photo 1 – Signs at Entrance

Photo 2 – Separators

Inspection Photos  
Location Name: Hunt 8-60-17A PAD  
Location ID: 457131



Photo 3 – VRUs and Compressors



Photo 4 – Tank Battery

Inspection Photos  
Location Name: Hunt 8-60-17A PAD  
Location ID: 457131



Photo 5 – Tank Battery Sign



Photo 6 – Tank Battery

Inspection Photos  
Location Name: Hunt 8-60-17A PAD  
Location ID: 457131



Photo 7 – Tank Battery



Photo 8 – LACT

Inspection Photos  
Location Name: Hunt 8-60-17A PAD  
Location ID: 457131



Photo 9 – ECDs



Photo 10 – Compressors

Inspection Photos  
Location Name: Hunt 8-60-17A PAD  
Location ID: 457131



Photo 11 – Wildlife Netting in disrepair



Photo 12 – Wildlife Netting in disrepair

Inspection Photos  
Location Name: Hunt 8-60-17A PAD  
Location ID: 457131



Photo 13 – Wildlife Netting is missing



Photo 14 – Deceased Bird in Wildlife Netting

Inspection Photos  
Location Name: Hunt 8-60-17A PAD  
Location ID: 457131



Photo 15 – Deceased Bird in Wildlife Netting




Photo 16 – Vault missing Opening Covers

**Inspection Photos**  
**Location Name: Hunt 8-60-17A PAD**  
**Location ID: 457131**



Energy and Carbon Management Commission  
40.66398, -104.12192, 4886-1ft  
02/14/2024 12:19:15

**Photo 17 – Gas Meter Houses**