

**Inspection Photos**  
**Location Name: Hunt 8-60-17B PAD**  
**Location ID: 457475**



**Photo 1 – Wellhead**



**Photo 2 – 24-Hour Contact Number does not reflect current Operator**

**Inspection Photos**  
**Location Name: Hunt 8-60-17B PAD**  
**Location ID: 457475**



**Photo 3 – Wellheads**



**Photo 4 – Wellheads – Fencing in disrepair**



**Inspection Photos**  
**Location Name: Hunt 8-60-17B PAD**  
**Location ID: 457475**



Energy and Carbon Management Commission  
40.66322, -104.11406, 4914.9ft  
02/14/2024 12:03:27

**Photo 5 – Wellhead**



Energy and Carbon Management Commission  
40.66322, -104.11405, 4912.8ft  
02/14/2024 12:03:32

**Photo 6 – 24-Hour Contact Number does not reflect current Operator**