

Inspection Photos

Location Name: CAERUS PICEANCE LLC CEDAR SPRINGS RANCH 11-11 (J11W) Pad

Location #: 334602



Photo # 6775 From entrance to location



Photo # 6776 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC CEDAR SPRINGS RANCH 11-11 (J11W) Pad

Location #: 334602




Photo # 6777 Location



Photo # 6778 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC CEDAR SPRINGS RANCH 11-11 (J11W) Pad

Location #: 334602



Feb 15, 2024 at 12:22:03 PM
CO

Photo # 6779 Location



Feb 15, 2024 at 12:15:18 PM
CO

Photo # 6780 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC CEDAR SPRINGS RANCH 11-11 (J11W) Pad

Location #: 334602



Feb 15, 2024 at 12:22:25 PM
CO

Photo # 6781 Location



Feb 15, 2024 at 12:21:19 PM
CO

Photo # 6782 Location



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC CEDAR SPRINGS RANCH 11-11 (J11W) Pad

Location #: 334602



Photo # 6783 Hole in liner/liner needs maintenance



Photo # 6784 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC CEDAR SPRINGS RANCH 11-11 (J11W) Pad

Location #: 334602



Photo # 6785 Debris



Photo # 6786 Debris