

Inspection Photos

Loc: 308564

Operator: EVERGREEN NATURAL RESOURCES LLC

Inspection Date: 2/16/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east along the access road at the gate near the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:308564 | Date: 2/16/2024

Inspection Photos



Photo 2. Facing southeast at the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:308564 | Date: 2/16/2024

Inspection Photos



Photo 3. There is an electric panel at north side of the location that is missing the cover. the tree growing around the utility seems to be a fire hazard.



Inspection Photos



Photo 4. There are stained soils at the wellhead.



Inspection Photos



Photo 5. There is oily fluid in the engine skid that needs to be cleaned up.

