

# Final Reclamation Inspection

February 16th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325888

Inspection Document #: 714000436

La Plata County, CO

Township: SESE 12 34N 8W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Dry Creek Federal 1  
Location ID: 325888

2/16/24  
+37.225447,-107.691457  
138° SE



Photo 1. View of the disturbance from the entrance facing center.

Inspection Photos  
Location Name: Dry Creek Federal 1  
Location ID: 325888

2/16/24  
+37.225079,-107.690837  
245° SW



**Photo 2.** View of the western interim reclamation area facing southwest.



Inspection Photos  
Location Name: Dry Creek Federal 1  
Location ID: 325888



**Photo 3.** View of rill erosion forming in the southern interim reclamation area.

Inspection Photos  
Location Name: Dry Creek Federal 1  
Location ID: 325888



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Additional stormwater BMPs have been installed in the western project area addressing previously cited stormwater CA identified in previous inspection doc #693903889

API #: 067-07124

Inspection Photos  
Location Name: Dry Creek Federal 1  
Location ID: 325888



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 5.** Reference area comprised of poa secunda, sagebrush and juniper.

API #: 067-07124