

Interim Reclamation and Stormwater Inspection

Date: 2/14/24

Operator: Noble Energy Inc. - 100322

Location ID: 328481

Inspection Document #: 713900378

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: Centennial State G34-689 Pad

Location ID: 328481



Photo 1. The photo was taken along the well location access road facing Southwest. The photo illustrates the access road has no stormwater issues.

Photo 2. The photo was taken at the well location facing Southeast. The photo illustrates the interim area around the wellheads has been mowed.

Inspection Photos

Location Name: Centennial State G34-689 Pad

Location ID: 328481



Photo 3. The photo was taken at the well location facing Southwest. Refer to the comment for photo 2.

Photo 4. The photo was taken at the well location facing East. Refer to the comment for photo 2.

Inspection Photos

Location Name: Centennial State G34-689 Pad

Location ID: 328481



Photo 5. The photo was taken at the tank battery location facing Northeast. The photo illustrates the portable bathroom is secured by a piece of wire attached to the bathroom vent.



Photo 6. The photo was taken at the tank battery location facing East. The photo illustrates the sediment trap on the North side of the facility.

Inspection Photos

Location Name: Centennial State G34-689 Pad

Location ID: 328481



Photo 7. The photo was taken at the tank battery location facing East. The photo illustrates the Southern boundary fence and stormwater BMP.



Photo 8. The photo was taken at the tank battery location facing Southwest. The photo illustrates the topsoil stockpile is vegetated successfully and has been mowed.

Inspection Photos

Location Name: Centennial State G34-689 Pad

Location ID: 328481



Photo 9. The photo was taken at the tank battery location facing West. The photo illustrates tumbleweeds building up around equipment.



Photo 10. The photo was taken at the tank battery location facing Southeast. The photo illustrates another area where tumbleweeds have built up.